Ohio EPA - Daily Discharge Monitoring Report - Form 4500

STATUS:

SUBMISSION ID:

160261

SEDO

American Energy Corp - Century Mine

PERMIT NUMBER: STATION CODE: Original 0 | | L 0 0 0 9 | | | | G | D

*0∏L0009∏≠*0

FACILITY: LOCATION: COUNTY: DISTRICT:

43521 Mayhugh Hill Rd Twp Hwy 88 Beallsville, OH 43716 Belmont

MONITORING PERIOD:
REPORTING LAB:

2011-02-01 To: 2011-02-28 TraDet William Thompson

ANALYST: NO DISCHARGE INDICATOR:

PARAMETER	Manganese, Total (Mn)						
PARAMETER CODE	01055			<u> </u>	<del></del>	<u> </u>	<del></del>
UNITS	ug/l						
FREQUENCY	1/2 Weeks						
SAMPLING TYPE	Grab			ļ			
2011-02-01				<u> </u>		<u> </u>	<u> </u>
2011-02-02				<u> </u>			<u> </u>
2011-02-03	914				J		
2011-02-04						<u> </u>	
2011-02-05				l		<u></u>	
2011-02-06							
2011-02-07							
2011-02-08	<u> </u>						
2011-02-09	L						
2011-02-10							
2011-02-11							
2011-02-12							
2011-02-13							
2011-02-14							
2011-02-15	628						
2011-02-16							
2011-02-17							
2011-02-18							
2011-02-19							
2011-02-20							
2011-02-21							
2011-02-22							
2011-02-23							
2011-02-24							
2011-02-25							
2011-02-26							
2011-02-27							
2011-02-28							
Minimum	628.0						
Maximum	914.0						
Average	771			ļ	<b></b>	<u></u>	
Count	2			1 5	nature of Responsible	Official on Author	
Name of Responsible Official or Authorized Representative		alty of law that I have pe	ersonally examined and		gnature of Responsible Represe	omicial or Authorized	Submission Date/Time
Cody Mozena	with the information submitted herein and based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.  Representative  Representative						2011-03- 12 10:03